



FOR IMMEDIATE RELEASE

Malaysia

IKEA is recalling METALLISK espresso maker for hob 0.4 l with the stainless steel safety valve, date stamps between 2040 and 2204, as the product can burst during use



IKEA urges all customers who own METALLISK espresso maker for hob 0.4 l with the stainless steel safety valve, date stamps between 2040 and 2204 (yyww), to stop using it and to contact IKEA for a full refund.

Safety is a top priority for IKEA and therefore we are recalling METALLISK espresso maker with the stainless-steel safety valve, date stamps between 2040 and 2204 (yyww), due to an increased risk of the product bursting during use. The risk has increased after a change of material and construction of the safety valve therefore only the products with the stainless steel safety valve (silver/grey in color), are included in the recall. No other units are affected by this recall. There are no reported incidents in Malaysia.

METALLISK espresso maker with the stainless-steel safety valve, date stamps between 2040 and 2204 (yyww), can be returned to any IKEA store at the Exchanges and Returns counter for a full refund. Proof of purchase (receipt) is not required.

For more information, please contact the IKEA Customer Contact Centre at 03-7952 7575.

IKEA apologises for any inconvenience this recall may cause.



- End -

For media enquiries, please contact:

IKEA Malaysia

Doris Chin

Marketing and PR Manager

Tel: +6016 778 9532

Email: doris.chin@ikano.asia

Archetype Agency Malaysia

Abby Doss

Tel: +60162153094

Email: ikea@archetype.co