







LACK



Design and Quality
IKEA of Sweden





104323

10x



112996

6x



110126

6x




101350

8x




101343

7x




100001


1x




1




2




3




4




5




6



7



8



9

