







HEMFJÄLLET




Design and Quality
IKEA of Sweden




1




1x




1x




2x




3x



8x




4x



1x




12x



2x




2x




5x

2




10124091

2x




10123231

2x



122998

4x




114334

4x




101354

4x




10096501

2x




10096503

4x



100214

2x




142626

2x



121122


2x



114254


6x

3



145718

8x



118331

8x




119253

16x




101345

8x




10040242


4x




2x



4x




8x




4x


1




2






3




4






6




7




4x


100214





9




10




11







12




13









16




17





18




19











22




23










25




26




27




28




29




30




31




32




33





FÖLUNGEN



HEMFJÄLLET

