







TAXÅSKLINT




Design and Quality
IKEA of Sweden







6x



4x



4x



3x




2x




14x




10x




1x



1x



4x




6x


2x

117228



1




2




6x




3




4




5






6




7




4x




8





9




10






11



12



13

